

# T estpassport Q&A



---

*La meilleure qualité le meilleur service*

<http://www.testpassport.fr>

Service de mise à jour gratuit pendant un an

**Exam : 922-111**

**Title : Communication Server 1000  
to RIs.6.0 Upgrades for  
Technicia**

**Version : Demo**

1.A customer with a Communication Server (CS) 1000E RIs. 5.5 HA system with two IPMGs and dual CPPM Signaling Servers is upgrading their system to release 6.0. The system is part of an IP Peer Network that includes a NRS database. Which upgrade step is correct?

- A.Use NRS Manager to download the NRS backup file to a compact flash.
- B.Use Element Manager to download the Signaling Server backup file to a compact.
- C.User NRS Manager to download the NRS backup file to the local PC.
- D.Use Element Manager to download the Signaling Server backup file to the local PC.

Answer:C

2.A customer with an existing Option 11C RIs. 5.5 chassis system is planning to upgrade to a Communication Server 1000E RIs. 6.0 Standard Availability. A CPPM Co-Resident Call Server and Signaling Server card will be installed. The system will automatically map small system Terminal Numbers to large system Terminal format during the upgrade. In this upgrade scenario, which actions must be completed manually? (Choose two.)

- A.Re-programming Digital Trunk Terminal Numbers with a new format.
- B.Programming the DSP daughterboards on the IP Media Gateway.
- CEntering the IP address for each IP Media Gateway in LD 97.
- D.Re-programming Tone Receiver Terminal Numbers with a new format.

Answer:B C

3.A customer with an existing Option 11C RIs. 5.5 chassis system is planning to upgrade to a Communication Server 1000E RIs. 6.0 Standard Availability. A CPPM card will be installed as a Co-Resident Call Server and Signaling Server during the upgrade. Which task must be completed prior to loading Linux Base onto the card? (Choose two.)

- A.The BIOS of the card must be updated to version 18.
- B.The S5 switch must be set to position 1.
- C.The CMOS settings must be reset to factory defaults.
- D.The on-board 1 GB Compact Flash must be installed.

Answer:A C

4.Click on the Exhibit button. You are upgrading a single site Option 11C RIs. 5.5 system to a Communication Server 1000E RIs. 6.0 Standard Availability with a single IP Media Gateway (MG) 1000E chassis. The customer is using a CPPM card from inventory as a CPPM Co-Resident Call Server and Signaling Server. Based on the output received when the card boots up, shown in the exhibit, what must be done before Linux Base can be loaded?

